

**ITB 2018-076**  
**RESURFACING, REPAIRS, AND RENOVATIONS OF OUTDOOR POOLS**  
**COVE POINT AQUATIC FACILITY**

<b>BID COMPARISON</b>						
<b>Bidder</b>	<b>Total Lump Sum Bid</b>	<b>Optional Add-On Pricing</b>				
		<b>1. Beam Repair Beyond Thirty-Five Feet (35')</b>			<b>2. Remove and Replace Existing Broken, Cracked, or Damaged tile</b>	<b>3. Remove and Replace Existing Brick Coping Stones Greater than the Twenty-Four (24) Specified and Included in Lump Sum Bid</b>
		<b>1a Additional Zero Inches (0") to Six Inches (6")</b>	<b>1b Additional Seven Inches (7") to Twelve Inches (12")</b>	<b>1c Additional Thirteen Inches (13") to Eighteen Inches (18")</b>		
		<b>per Lineal Foot</b>				
Millennium Pool Services	\$122,605.00	\$36.00	\$64.00	\$90.00	\$36.00	\$49.00
Winkler Pool Management	\$128,515.00	\$110.00	\$155.00	\$199.00	\$22.50	\$49.95
Olympia Swimming Pool	\$142,788.00	\$12.00	\$30.00	\$65.00	\$22.00	\$32.00
KINS, Inc. dba Aquatic Specialists	\$148,202.00	\$38.30	\$67.65	\$93.62	\$18.58	\$50.82
High Sierra Pools	\$170,000.00	\$42.20	\$74.00	\$103.16	\$25.00	\$74.00